


「 Chapter 2 4DOF Robot Arm 」



「 4DOF Robot Arm 」

► 00: Assembly Guide of Mainboard ELF



1x328P MicroChip Module V1.0



1xWeeeMake Bluetooth 4.1 Module



1xLight Sensor (Pin)



1xIR Receiver (Pin)



1xSound Sensor (Pin)



1xELF Mainboard



1xELF Mainboard Lid




1xELF Mainboard Base



1xRGB LED - 8 (Pin)




2xDC/Encoder Motor Driver



「4DOF Robot Arm」

▶ 00: Assembly Guide of Mainboard ELF



「 4DOF Robot Arm 」

► 00: Assembly Guide of Mainboard ELF



4xScrew M4*8




2xLinkage 0208-24



1xBeam 1030-100-B




1xMainboard ELF



「 4DOF Robot Arm 」

▶ 00: Assembly Guide of Mainboard ELF



Tips:

The default sensors on mainboard ELF is installed as follows:

Port 1 - Light Sensor Port 2 - IR Receiver Port 3 & 4 - DC/Encoder Motor Driver Port 5 - Sound Sensor

MCU Port - 328P Micro Chip

Communication Port - Bluetooth Module

Special port - RGB LED -8 Module

「 4DOF Robot Arm 」


► 01: Pre-plug Nut M4 into the Rail of the Slide Beam 0824-96




1xSlide Beam 0824-96



2xNut M4



Tips:
Put two Nut M4 in the slot of slide beam 0824-96, so you can assemble battery holder later. If missed this step, battery holder cannot be fixed.



► 02: Assemble the Base Structure



1xBeam 1030-100



2xBeam 1030-132





1xSlide Beam 0824-96 (Nut M4 in slot)



2xLinkage 0208-24



8xScrew M4*8



Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」


22

► 02: Assemble the Base Structure

 2xBeam 0410-154

 4xScrew M4*10

 4xNut M4




Tips:

Please pay attention to the hole position and direction.

► 02: Assemble the Base Structure

 2xBeam 0410-130


 4xScrew M4*8



「 4DOF Robot Arm 」


► 03: Assemble the 18650 Lithium Battery Holder

-  2x18650 Lithium Battery
-  1xLithium Battery Holder Lid
-  1xLithium Battery Holder
-  2xScrew M4*8



► 04: Assemble Vertical Fixed Beam

-  1xBeam 1030-100
-  1xBeam 1030-100-B
-  4xScrew M4*8



「 4DOF Robot Arm 」

24

► 05: Assemble Horizontal Encoder DC Motor 25 (188RPM)





1x25 Motor Bracket



1xEncoder DC Motor-25 9V188RPM



2xCountersunk Head Screw M3*6



Tips:

Please pay attention to the hole position and direction.

► 06: Assemble 8T Plastic Gear



1xBeam 0410-130



1xEncoder DC Motor-25 9V188RPM Assembly





1x8T-Plastic Gear V1.0 (Flat Hole)



2xScrew M4*8



1xScrew M2*4



Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

► 07: Assemble the 56T Plastic Gear



2x56T-Plastic Gear V1.0



1xDriving Flange Hub 4mm



1xThreaded shaft 4-48



1xShaft Collar - 4mm



1xFlange Copper Bearing 4*8*3.5



2xNylon Spacer 4*7*3



2xNut M4



1xHeadless Screw M4*3

Hole 1

Hole 8

Tips:

Please pay attention to the hole position and direction.

► 08: Assemble Horizontal Rotary Shaft



1xHorizontal rotary shaft assembly



2xScrew M4*8

Front

Back

Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

26

► 09: Assemble DC Motor 25 (50RPM)




1x25 Motor Bracket



1xDC Motor-25 (50RPM)



2xCountersunk Head Screw M3*6



Tips:

Please pay attention to the hole position and direction.

► 09: Assemble DC Motor 25 (50RPM)




1xBeam 0410-106



1xDC Motor-25 (50RPM) Assembly



2xScrew M4*8



Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」


► 10: Assemble 8T Plastic Gear



1x8T-Plastic Gear V1.0 (Flat Hole)



1xScrew M2*4



► 11: Assemble First Stage Free Arm




1xBeam 1030-68



1xBeam 0410-106



4xScrew M4*8



Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

28

► 12: Assemble First Stage Free Arm to the Base




1xFirst Stage Free Arm Assembly



2xAluminum Column 4*6*6



2xScrew M4*25



Tips:

Please pay attention to the hole position and direction.

► 13: Assemble Encoder DC Motor -25 (188RPM)




1x25 Motor Bracket



1xEncoder DC Motor-25 9V188RPM



2xCountersunk Head Screw M3*6




Tips:

Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

► 13: Assemble Encoder DC Motor -25 (188RPM)

-  1xBeam 0410-186
-  1xEncoder DC Motor-25 9V188RPM Assembly
-  1x8T-Plastic Gear V1.0 (Flat Hole)
-  2xScrew M4*8
-  1xScrew M2*4




Tips:

Please pay attention to the hole position and direction.

► 14: Assemble Intermediate Free Arm

-  1xBeam 0410-186
-  2xSlide Beam 0824-32
-  8xScrew M4*8



Tips:


Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

30

► 14: Assemble Intermediate Free Arm


-  1x56T-Plastic Gear V1.0
-  1xNylon Lock Nut M4
-  1xScrew M4*20



Tips: Please pay attention to the hole position and direction.

► 15: Assemble Intermediate Free Arm to the Base

-  1xIntermediate Free Arm Assembly
-  1xFlat Shaft 4-80
-  1xFlange Copper Bearing 4*8*3.5
-  3xHeadless Screw M4*3
-  3xShaft Collar - 4mm



Tips: Please pay attention to the hole position and direction.

「 4DOF Robot Arm 」

► 16: Assemble End Free Arm



2xBeam 0410-106



1xBeam 0824-16-A



1x56T-Plastic Gear V1.0




4xScrew M4*8



1xScrew M4*20



1xNylon Lock Nut M4



Tips: Please pay attention to the hole position and direction.

► 16: Assemble End Free Arm



1xEnd Free Arm Assembly



1xFlat Shaft 4-56



1xFlange Copper Bearing 4*8*3.5




3xHeadless Screw M4*3



3xShaft Collar - 4mm



2xNylon Spacer 4*7*3



「 4DOF Robot Arm 」

32


► 17: Assemble ELF Mainboard Assembly to Base



1xMainboard ELF Assembly



2xScrew M4*8



Tips:Please pay attention to the hole position and direction.

► 18: Assemble Bracket U1



1xBracket U1




1xMG995 Metal Robot Gripper



4xScrew M4*8




4xNut M4



「 4DOF Robot Arm 」

► 19: Assemble Robot Gripper & RJ11 Adapter


-  1xMG995 Metal Robot Gripper Assembly
-  1xRJ11 Adapter V1.0 Module
-  2xScrew M4*25
-  2xScrew M4*35
-  4xNut M4




Tips: Please pay attention to the hole position and direction.

► 20: Wiring

-  1xEncoder Motor Wire-25cm
-  1xEncoder Motor Wire-70cm
-  1xDC Motor Wire-35cm
-  1xDC Motor Wire-80cm
-  1xPower cord 5.5-2.1
-  1xRJ11 Cable-20cm



「 Wiring 」



「 Completion Diagram 」

